

Web site: www.ecotek.eu
email: help@ecotek.eu

CB-26P Fitting position

Hyundai 2.0 Coupe



This is one fitted to a Hyundai 2 Litre Coupe and gives an 8%+ improvement in consumption and "a bit more at the top end" according to the owner. You can see the CB-26P just below the air intake tubing - to expand the picture click on it.

Fitting was a bit more awkward here - to get the best results it sometimes helps to remove the vacuum hose completely and fit the device when the hose is off the car - then simply replace the hose, warm up the engine then tune the device.

Significant improvements in throttle response from most early Hyundai engines are common.